Oil Field Environmental Incident Summary

Responsible Party: ENDURO OPERATING, LLC
Well Operator: ENDURO OPERATING, LLC
Well Name: EAST FLAXTON-MADISON UNIT 12

Field Name: FLAXTON Well File #: 2403

Date Incident:12/5/2014Time Incident:10:00Facility ID Number:County:BURKETwp:163Rng:90Sec:29Qtr:

Location Description:

Submitted By: Scott Hunskor Received By:

Contact Person: Scott Hunskor

777 MAIN STREET

SUITE 800

FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 15 Barrels 15 Barrels 15 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 10/19/2015 Clean Up Concluded: 12/9/2014

Risk Evaluation:

none

Areal Extent:

Fitting failed causing leak. Brine leaked through gopher hole in dike, but stayed on facility site

Potential Environmental Impacts:

none

Action Taken or Planned:

Shut well in, isolate leak, scrape up affected soil on location and store in three sided container to be later hauled to approved waste facility. Repair and inspect fittings in injection house, repair dike that had gopher holes.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 12/5/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.